



Construction Materials Testing
Waterline Installation—Backfill Compaction
Corley Farms Unit 1
Boerne, Texas

InTEC Project No. S212188-2

October 18, 2023

Pulte Homes Of Texas, L.P.
1718 Dry Creek Way, Suite 120
San Antonio, Texas 78259



Integrated Testing and Engineering Company of San Antonio, L.P.

Geotechnical & Environmental Engineering • Construction Services • Geologic Assessment

E.A. Palaniappan, Ph.D., P.E.
Murali Subramaniam, Ph.D., P.E.
Kausi Subramaniam, B.S.

October 18, 2023

Pulte Homes of Texas, L.P.
1718 Dry Creek Way, Suite 120
San Antonio, Texas 78259

Attention: Mr. Cameron Sasko

Re: Construction Materials Testing
Waterline Installation – Backfill Compaction
Corley Farms Unit 1
Boerne, Texas

InTEC Project #: S212188-2

Gentlemen:

Integrated Testing and Engineering Company of San Antonio, L.P. (InTEC) performed compaction evaluation at the above referenced project site between March 1, 2022 and April 14, 2023.

Field density tests were performed on an "on call" basis by the contractor. Full time observation of fill placement was not performed. Laboratory Compaction and Field Density Tests results at the above referenced project site are presented for your review.

We appreciate and wish to thank you for the opportunity to be of service to you on this project. If we can be of additional assistance, or if you have any questions, please call us.

Respectfully Submitted,
InTEC of San Antonio, L.P.

Murali Subramaniam, Ph.D., P.E.

Copies Submitted: Above (1)



[Signature]
10/19/2023

LABORATORY COMPACTION TEST RESULTS



TESTED FOR:

Pulte Homes of Texas, L.P.
1718 Dry Creek Way, Suite 120
San Antonio, Texas

PROJECT:

Compaction Evaluation
Corley Farms Unit 1
Boerne, Texas

PROJECT NO: S212188

SOIL ID	17648		
SOIL TYPE	Tan gravelly clay		
TEST METHOD	ASTM D1557		
SAMPLE DATE	12/14/2021		
MAXIMUM DRY DENSITY	119.9 PCF		
OPTIMUM WATER CONTENT	12.5 %		

DISTRIBUTION:	Above (1)		
---------------	-----------	--	--

Respectfully submitted

murali

Murali Subramaniam, Ph.D., P.E.

Integrated Engineering and Testing Company of San Antonio, L.P.

12028 Radium, San Antonio, Texas 78216

Phone: (210) 525-9033

Fax: (210) 525-9032

LABORATORY COMPACTION TEST RESULTS

**TESTED FOR:**

Pulte Homes of Texas, L.P.
1718 Dry Creek Way, Suite 120
San Antonio, Texas

PROJECT:

Compaction Evaluation
Corley Farms Unit 1
Boerne, Texas

PROJECT NO: S212188

SOIL ID	17649		
SOIL TYPE	Tan to brown gravelly clay		
TEST METHOD	ASTM D1557		
SAMPLE DATE	12/14/2021		
MAXIMUM DRY DENSITY	125.1 PCF		
OPTIMUM WATER CONTENT	10.9 %		

DISTRIBUTION:	Above (1)		
---------------	-----------	--	--

Respectfully submitted

murali

Murali Subramaniam, Ph.D., P.E.

Integrated Engineering and Testing Company of San Antonio, L.P.

12028 Radium, San Antonio, Texas 78216

Phone: (210) 525-9033

Fax: (210) 525-9032



InTEC of San Antonio
12028 Radium
San Antonio, TX 78216
Phone: 210-525-9033

Compaction Evaluation

Report Date: 10/18/2023
Test Method: ASTM D6938, Tex 115E

Client:

Pulte Homes of Texas, LP
1718 Dry Creek Way Suite 120
San Antonio, TX 78259

Project:

S212188
Corley Farms Unit 1
29.737543477901177, -98.71426779610178
Boerne, TX

Test Results															
Test #	Retest Of	Test Date	Proctor ID	Method	Soil Classification	Optimum Moisture (%)	Maximum Dry Density (pcf)	In Place Moisture (%)	In Place Dry Density (pcf)	In Place Wet Density (pcf)	Probe Depth (in)	Percent Compaction	Min Comp. (%)	Optimum Moisture Tolerance (%)	Remark
153		03/01/22	U17648		GC	12.5	119.9	11.5	118.2	131.8	6	98.6	95	-2 / 2	C
154		03/01/22	U17648		GC	12.5	119.9	10.9	117.3	130.1	6	97.8	95	-2 / 2	C
157		03/01/22	U17648		GC	12.5	119.9	11.6	118.2	131.9	6	98.6	95	-2 / 2	C
158		03/01/22	U17648		GC	12.5	119.9	12.5	117.8	132.5	6	98.2	95	-2 / 2	C
161		03/02/22	U17648		GC	12.5	119.9	12.2	118.2	132.6	6	98.6	95	-2 / 2	C
162		03/02/22	U17648		GC	12.5	119.9	11.8	118.3	132.3	6	98.7	95	-2 / 2	C
165		03/02/22	U17649		GC	10.9	125.1	12.8	123.8	139.6	6	99.0	95	-2 / 2	C
166		03/02/22	U17649		GC	10.9	125.1	11.6	124.3	138.7	6	99.4	95	-2 / 2	C
Test Information															
Test #	Test Location							Elevation	Reference		Gauge Make / Model / SN / Calibrated			Field Technician	
153	Water Main: White Barn Cove, Block 3 Lot 7								1st Lift		Troxler / 3430 / 38292 / 03/30/2021			Pereida, Gerald	
154	Water Main: White Barn Cove, Block 1 Lot 3								1st Lift		Troxler / 3430 / 38292 / 03/30/2021			Pereida, Gerald	
157	Water Main: White Barn Cove, Block 3 Lot 6								2nd Lift		Troxler / 3430 / 38292 / 03/30/2021			Pereida, Gerald	
158	Water Main: White Barn Cove, Block 1 Lot 3								2nd Lift		Troxler / 3430 / 38292 / 03/30/2021			Pereida, Gerald	
161	Water Main: White Barn Cove, Block 3 Lot 7								3rd Lift		Troxler / 3430 / 38292 / 03/30/2021			Pereida, Gerald	
162	Water Main: White Barn Cove, Block 1 Lot 3								3rd Lift		Troxler / 3430 / 38292 / 03/30/2021			Pereida, Gerald	
165	Water Main: Water Line A STA 15+00								1st Lift		Troxler / 3430 / 38292 / 03/30/2021			Pereida, Gerald	
166	Water Main: Water Line A STA 17+00								1st Lift		Troxler / 3430 / 38292 / 03/30/2021			Pereida, Gerald	
Remarks					Comments										
C: Compliant					Tests are "Direct Transmission" (Method A) unless probe depth is noted as "Backscatter". Gauge calibration data on file with the testing agency.										

Testing performed when called in.
InTEC did not observe the installation of the material.
Testing directed by the City Inspector when present.
Test results apply only to the specific locations and materials noted and may not represent any other locations or elevations.



InTEC of San Antonio
12028 Radium
San Antonio, TX 78216
Phone: 210-525-9033

Compaction Evaluation

Report Date: 10/18/2023
Test Method: ASTM D6938, Tex 115E

Client:

Pulte Homes of Texas, LP
1718 Dry Creek Way Suite 120
San Antonio, TX 78259

Project:

S212188
Corley Farms Unit 1
29.737543477901177, -98.71426779610178
Boerne, TX

Test Results															
Test #	Retest Of	Test Date	Proctor ID	Method	Soil Classification	Optimum Moisture (%)	Maximum Dry Density (pcf)	In Place Moisture (%)	In Place Dry Density (pcf)	In Place Wet Density (pcf)	Probe Depth (in)	Percent Compaction	Min Comp. (%)	Optimum Moisture Tolerance (%)	Remark
167		03/02/22	U17649		GC	10.9	125.1	10.8	125.3	138.8	6	100.2	95	-2 / 2	C
168		03/02/22	U17649		GC	10.9	125.1	9.9	123.3	135.5	6	98.6	95	-2 / 2	C
169		03/03/22	U17648		GC	12.5	119.9	12.6	118.5	133.4	8	98.8	95	-2 / 2	C
170		03/03/22	U17648		GC	12.5	119.9	13.4	120.8	137.0	8	100.8	95	-2 / 2	C
173		03/03/22	U17648		GC	12.5	119.9	12.6	117.8	132.6	8	98.2	95	-2 / 2	C
174		03/03/22	U17648		GC	12.5	119.9	11.8	117.8	131.7	8	98.2	95	-2 / 2	C
175		03/03/22	U17648		GC	12.5	119.9	11.6	116.8	130.3	8	97.4	95	-2 / 2	C
176		03/03/22	U17648		GC	12.5	119.9	12.3	120.8	135.7	8	100.8	95	-2 / 2	C
Test Information															
Test #	Test Location						Elevation	Reference		Gauge Make / Model / SN / Calibrated			Field Technician		
167	Water Main: White Barn Cove, Block 3 Lot 7							4th Lift		Troxler / 3430 / 38292 / 03/30/2021			Pereida, Gerald		
168	Water Main: White Barn Cove, Block 1 Lot 4							4th Lift		Troxler / 3430 / 38292 / 03/30/2021			Pereida, Gerald		
169	Water Main: Water Line A STA 15+00							2nd Lift		Troxler / 3430 / 38292 / 03/30/2021			Pereida, Gerald		
170	Water Main: Water Line A STA 17+00							2nd Lift		Troxler / 3430 / 38292 / 03/30/2021			Pereida, Gerald		
173	Water Main: Homestead Ridge, 300' W of Rustic Barn Lane							1st Lift		Troxler / 3430 / 38292 / 03/30/2021			Pereida, Gerald		
174	Water Main: Homestead Ridge, 600' W of Rustic Barn Lane							1st Lift		Troxler / 3430 / 38292 / 03/30/2021			Pereida, Gerald		
175	Water Main: Homestead Ridge, 900' W of Rustic Barn Lane							1st Lift		Troxler / 3430 / 38292 / 03/30/2021			Pereida, Gerald		
176	Water Main: Water Line A STA 12+00							1st Lift		Troxler / 3430 / 38292 / 03/30/2021			Pereida, Gerald		
Remarks					Comments										
C: Compliant					Tests are "Direct Transmission" (Method A) unless probe depth is noted as "Backscatter". Gauge calibration data on file with the testing agency.										

Testing performed when called in.
InTEC did not observe the installation of the material.
Testing directed by the City Inspector when present.
Test results apply only to the specific locations and materials noted and may not represent any other locations or elevations.



InTEC of San Antonio
12028 Radium
San Antonio, TX 78216
Phone: 210-525-9033

Compaction Evaluation

Report Date: 10/18/2023
Test Method: ASTM D6938, Tex 115E

Client:

Pulte Homes of Texas, LP
1718 Dry Creek Way Suite 120
San Antonio, TX 78259

Project:

S212188
Corley Farms Unit 1
29.737543477901177, -98.71426779610178
Boerne, TX

Test Results															
Test #	Retest Of	Test Date	Proctor ID	Method	Soil Classification	Optimum Moisture (%)	Maximum Dry Density (pcf)	In Place Moisture (%)	In Place Dry Density (pcf)	In Place Wet Density (pcf)	Probe Depth (in)	Percent Compaction	Min Comp. (%)	Optimum Moisture Tolerance (%)	Remark
177		03/03/22	U17649		GC	10.9	125.1	10.9	124.6	138.2	8	99.6	95	-2 / 2	C
178		03/03/22	U17649		GC	10.9	125.1	11.3	123.8	137.8	8	99.0	95	-2 / 2	C
179		03/03/22	U17649		GC	10.9	125.1	10.9	124.7	138.3	8	99.7	95	-2 / 2	C
180		03/03/22	U17649		GC	10.9	125.1	11.5	125.6	140.0	8	100.4	95	-2 / 2	C
181		03/03/22	U17649		GC	10.9	125.1	10.8	122.6	135.8	8	98.0	95	-2 / 2	C
184		03/04/22	U17649		GC	10.9	125.1	9.7	125.6	137.8	8	100.4	95	-2 / 2	C
185		03/04/22	U17649		GC	10.9	125.1	11.3	123.8	137.8	8	99.0	95	-2 / 2	C
188		03/04/22	U17649		GC	10.9	125.1	10.1	123.9	136.4	8	99.0	95	-2 / 2	C
Test Information															
Test #	Test Location							Elevation	Reference		Gauge Make / Model / SN / Calibrated			Field Technician	
177	Water Main: Homestead Ridge, 325' W of Rustic Barn Lane								2nd Lift		Troxler / 3430 / 38292 / 03/30/2021			Pereida, Gerald	
178	Water Main: Homestead Ridge, 650' W of Rustic Barn Lane								2nd Lift		Troxler / 3430 / 38292 / 03/30/2021			Pereida, Gerald	
179	Water Main: Homestead Ridge, 850' W of Rustic Barn Lane								2nd Lift		Troxler / 3430 / 38292 / 03/30/2021			Pereida, Gerald	
180	Water Main: Water Line A STA 12+00								2nd Lift		Troxler / 3430 / 38292 / 03/30/2021			Pereida, Gerald	
181	Water Main: Water Line A STA 14+00								2nd Lift		Troxler / 3430 / 38292 / 03/30/2021			Pereida, Gerald	
184	Water Main: Water Line A STA 12+00								3rd Lift		Troxler / 3430 / 38292 / 03/30/2021			Pereida, Gerald	
185	Water Main: Water Line A STA 14+00								3rd Lift		Troxler / 3430 / 38292 / 03/30/2021			Pereida, Gerald	
188	Water Main: Water Line A STA 12+00								4th Lift		Troxler / 3430 / 38292 / 03/30/2021			Pereida, Gerald	
Remarks					Comments										
C: Compliant					Tests are "Direct Transmission" (Method A) unless probe depth is noted as "Backscatter". Gauge calibration data on file with the testing agency.										

Testing performed when called in.
InTEC did not observe the installation of the material.
Testing directed by the City Inspector when present.
Test results apply only to the specific locations and materials noted and may not represent any other locations or elevations.



InTEC of San Antonio
12028 Radium
San Antonio, TX 78216
Phone: 210-525-9033

Compaction Evaluation

Report Date: 10/18/2023
Test Method: ASTM D6938, Tex 115E

Client:

Pulte Homes of Texas, LP
1718 Dry Creek Way Suite 120
San Antonio, TX 78259

Project:

S212188
Corley Farms Unit 1
29.737543477901177, -98.71426779610178
Boerne, TX

Test Results															
Test #	Retest Of	Test Date	Proctor ID	Method	Soil Classification	Optimum Moisture (%)	Maximum Dry Density (pcf)	In Place Moisture (%)	In Place Dry Density (pcf)	In Place Wet Density (pcf)	Probe Depth (in)	Percent Compaction	Min Comp. (%)	Optimum Moisture Tolerance (%)	Remark
190		03/07/22	U17649		GC	10.9	125.1	9.7	124.3	136.4	8	99.4	95	-2 / 2	C
191		03/07/22	U17649		GC	10.9	125.1	11.2	125.7	139.8	8	100.5	95	-2 / 2	C
192		03/07/22	U17649		GC	10.9	125.1	10.5	123.8	136.8	8	99.0	95	-2 / 2	C
193		03/07/22	U17649		GC	10.9	125.1	11.3	126.8	141.1	8	101.4	95	-2 / 2	C
194		03/07/22	U17649		GC	10.9	125.1	10.2	124.2	136.9	8	99.3	95	-2 / 2	C
195		03/07/22	U17649		GC	10.9	125.1	10.1	123.8	136.3	8	99.0	95	-2 / 2	C
196		03/08/22	U17649		GC	10.9	125.1	9.7	124.4	136.5	8	99.4	95	-2 / 2	C
197		03/08/22	U17649		GC	10.9	125.1	10.0	126.5	139.2	8	101.1	95	-2 / 2	C
Test Information															
Test #	Test Location							Elevation	Reference		Gauge Make / Model / SN / Calibrated			Field Technician	
190	Water Main: Water Line A STA 5+00								1st Lift		Troxler / 3430 / 38292 / 03/30/2021			Pereida, Gerald	
191	Water Main: Water Line A STA 6+50								1st Lift		Troxler / 3430 / 38292 / 03/30/2021			Pereida, Gerald	
192	Water Main: Water Line A STA 9+00								1st Lift		Troxler / 3430 / 38292 / 03/30/2021			Pereida, Gerald	
193	Water Main: Water Line A STA 5+50								2nd Lift		Troxler / 3430 / 38292 / 03/30/2021			Pereida, Gerald	
194	Water Main: Water Line A STA 7+00								2nd Lift		Troxler / 3430 / 38292 / 03/30/2021			Pereida, Gerald	
195	Water Main: Water Line A STA 9+50								2nd Lift		Troxler / 3430 / 38292 / 03/30/2021			Pereida, Gerald	
196	Water Main: Water Line A STA 5+75								3rd Lift		Troxler / 3430 / 38292 / 03/30/2021			Pereida, Gerald	
197	Water Main: Water Line A STA 6+75								3rd Lift		Troxler / 3430 / 38292 / 03/30/2021			Pereida, Gerald	
Remarks					Comments										
C: Compliant					Tests are "Direct Transmission" (Method A) unless probe depth is noted as "Backscatter". Gauge calibration data on file with the testing agency.										

Testing performed when called in.
InTEC did not observe the installation of the material.
Testing directed by the City Inspector when present.
Test results apply only to the specific locations and materials noted and may not represent any other locations or elevations.



InTEC of San Antonio
12028 Radium
San Antonio, TX 78216
Phone: 210-525-9033

Compaction Evaluation

Report Date: 10/18/2023
Test Method: ASTM D6938, Tex 115E

Client:

Pulte Homes of Texas, LP
1718 Dry Creek Way Suite 120
San Antonio, TX 78259

Project:

S212188
Corley Farms Unit 1
29.737543477901177, -98.71426779610178
Boerne, TX

Test Results															
Test #	Retest Of	Test Date	Proctor ID	Method	Soil Classification	Optimum Moisture (%)	Maximum Dry Density (pcf)	In Place Moisture (%)	In Place Dry Density (pcf)	In Place Wet Density (pcf)	Probe Depth (in)	Percent Compaction	Min Comp. (%)	Optimum Moisture Tolerance (%)	Remark
198		03/08/22	U17649		GC	10.9	125.1	12.9	126.3	142.6	8	101.0	95	-2 / 2	C
199		03/08/22	U17649		GC	10.9	125.1	10.6	125.3	138.6	6	100.2	95	-2 / 2	C
200		03/08/22	U17649		GC	10.9	125.1	9.7	124.3	136.4	6	99.4	95	-2 / 2	C
201		03/08/22	U17649		GC	10.9	125.1	10.1	123.8	136.3	6	99.0	95	-2 / 2	C
426		12/01/22	U17648		GC	12.5	119.9	13.2	120.4	136.3	6	100.4	95	-2 / 2	C
427		12/01/22	U17648		GC	12.5	119.9	12.5	118.7	133.5	6	99.0	95	-2 / 2	C
529		03/31/23	U17648		GC	12.5	119.9	14.2	120.5	137.6	6	100.5	95	-2 / 2	C
530		03/31/23	U17648		GC	12.5	119.9	13.5	118.9	135.0	6	99.2	95	-2 / 2	C
Test Information															
Test #	Test Location						Elevation	Reference		Gauge Make / Model / SN / Calibrated			Field Technician		
198	Water Main: Water Line A STA 9+10							3rd Lift		Troxler / 3430 / 38292 / 03/30/2021			Pereida, Gerald		
199	Water Main: Water Line A STA 5+50							4th Lift		Troxler / 3430 / 38292 / 03/30/2021			Pereida, Gerald		
200	Water Main: Water Line A STA 7+00							4th Lift		Troxler / 3430 / 38292 / 03/30/2021			Pereida, Gerald		
201	Water Main: Water Line A STA 10+00							4th Lift		Troxler / 3430 / 38292 / 03/30/2021			Pereida, Gerald		
426	Water Main: Water Line A STA 4+01							1st Lift		Troxler / 3430 / 38292 / 07/26/2022			Pereida, Gerald		
427	Water Main: Water Line A STA 4+00							2nd Lift		Troxler / 3430 / 38292 / 07/26/2022			Pereida, Gerald		
529	Water Main: Homestead Ridge, Block 4 Lot 903							1st Lift		Troxler / 3430 / 38292 / 07/26/2022			Pereida, Gerald		
530	Water Main: Homestead Ridge - Left STA 11+00							1st Lift		Troxler / 3430 / 38292 / 07/26/2022			Pereida, Gerald		
Remarks					Comments										
C: Compliant					Tests are "Direct Transmission" (Method A) unless probe depth is noted as "Backscatter". Gauge calibration data on file with the testing agency.										

Testing performed when called in.
InTEC did not observe the installation of the material.
Testing directed by the City Inspector when present.
Test results apply only to the specific locations and materials noted and may not represent any other locations or elevations.



InTEC of San Antonio
12028 Radium
San Antonio, TX 78216
Phone: 210-525-9033

Compaction Evaluation

Report Date: 10/18/2023
Test Method: ASTM D6938, Tex 115E

Client:

Pulte Homes of Texas, LP
1718 Dry Creek Way Suite 120
San Antonio, TX 78259

Project:

S212188
Corley Farms Unit 1
29.737543477901177, -98.71426779610178
Boerne, TX

Test Results															
Test #	Retest Of	Test Date	Proctor ID	Method	Soil Classification	Optimum Moisture (%)	Maximum Dry Density (pcf)	In Place Moisture (%)	In Place Dry Density (pcf)	In Place Wet Density (pcf)	Probe Depth (in)	Percent Compaction	Min Comp. (%)	Optimum Moisture Tolerance (%)	Remark
531		04/03/23	L16257		GC	12.8	119.9	13.4	118.2	134.0	6	98.6	95	-2 / 2	C
532		04/03/23	L16257		GC	12.8	119.9	13.5	117.6	133.5	6	98.1	95	-2 / 2	C
533		04/03/23	U17648		GC	12.5	119.9	10.5	118.6	131.1	6	98.9	95	-2 / 2	C
534		04/04/23	U17648		GC	12.5	119.9	11.8	120.4	134.6	6	100.4	95	-2 / 2	C
535		04/04/23	L16257		GC	12.8	119.9	12.2	120.4	135.1	6	100.4	95	-2 / 2	C
536		04/05/23	U17648		GC	12.5	119.9	10.6	118.9	131.5	6	99.2	95	-2 / 2	C
537		04/05/23	U17648		GC	12.5	119.9	11.3	117.8	131.1	6	98.2	95	-2 / 2	C
538		04/05/23	U17648		GC	12.5	119.9	12.3	118.1	132.6	6	98.5	95	-2 / 2	C
Test Information															
Test #	Test Location						Elevation	Reference		Gauge Make / Model / SN / Calibrated			Field Technician		
531	Water Main: Homestead Ridge, Block 4 Lot 903							2nd Lift		Troxler / 3430 / 38292 / 07/26/2022			Pereida, Gerald		
532	Water Main: Homestead Ridge - Left STA 11+00							2nd Lift		Troxler / 3430 / 38292 / 07/26/2022			Pereida, Gerald		
533	Water Main: Homestead Ridge, Block 4 Lot 903							3rd Lift		Troxler / 3430 / 38292 / 07/26/2022			Pereida, Gerald		
534	Water Main: Homestead Ridge, Block 4 Lot 903							4th Lift		Troxler / 3430 / 38292 / 07/26/2022			Pereida, Gerald		
535	Water Main: Homestead Ridge, Block 4 Lot 903							5th Lift		Troxler / 3430 / 38292 / 07/26/2022			Pereida, Gerald		
536	Water Main: Homestead Ridge - Right STA 11+00							1st Lift		Troxler / 3430 / 38292 / 07/26/2022			Pereida, Gerald		
537	Water Main: Homestead Ridge - Right STA 8+00							1st Lift		Troxler / 3430 / 38292 / 07/26/2022			Pereida, Gerald		
538	Water Main: Homestead Ridge - Right STA 11+00							2nd Lift		Troxler / 3430 / 38292 / 07/26/2022			Pereida, Gerald		
Remarks					Comments										
C: Compliant					Tests are "Direct Transmission" (Method A) unless probe depth is noted as "Backscatter". Gauge calibration data on file with the testing agency.										

Testing performed when called in.
InTEC did not observe the installation of the material.
Testing directed by the City Inspector when present.
Test results apply only to the specific locations and materials noted and may not represent any other locations or elevations.



InTEC of San Antonio
12028 Radium
San Antonio, TX 78216
Phone: 210-525-9033

Compaction Evaluation

Report Date: 10/18/2023
Test Method: ASTM D6938, Tex 115E

Client:

Pulte Homes of Texas, LP
1718 Dry Creek Way Suite 120
San Antonio, TX 78259

Project:

S212188
Corley Farms Unit 1
29.737543477901177, -98.71426779610178
Boerne, TX

Test Results															
Test #	Retest Of	Test Date	Proctor ID	Method	Soil Classification	Optimum Moisture (%)	Maximum Dry Density (pcf)	In Place Moisture (%)	In Place Dry Density (pcf)	In Place Wet Density (pcf)	Probe Depth (in)	Percent Compaction	Min Comp. (%)	Optimum Moisture Tolerance (%)	Remark
539		04/05/23	U17648		GC	12.5	119.9	13.5	117.6	133.5	6	98.1	95	-2 / 2	C
540		04/10/23	U17648		GC	12.5	119.9	11.6	119.2	133.0	6	99.4	95	-2 / 2	C
541		04/10/23	U17648		GC	12.5	119.9	13.4	117.8	133.6	6	98.2	95	-2 / 2	C
542		04/10/23	U17648		GC	12.5	119.9	11.8	118.6	132.6	6	98.9	95	-2 / 2	C
543		04/10/23	U17648		GC	12.5	119.9	12.4	117.6	132.2	6	98.1	95	-2 / 2	C
544		04/11/23	U17648		GC	12.5	119.9	11.1	119.2	132.4	6	99.4	95	-2 / 2	C
545		04/11/23	U17648		GC	12.5	119.9	12.3	118.7	133.3	6	99.0	95	-2 / 2	C
546		04/11/23	L16257		GC	12.8	119.9	10.9	118.7	131.6	6	99.0	95	-2 / 2	C
Test Information															
Test #	Test Location						Elevation	Reference		Gauge Make / Model / SN / Calibrated			Field Technician		
539	Water Main: Homestead Ridge - Right STA 8+00							2nd Lift		Troxler / 3430 / 38292 / 07/26/2022			Pereida, Gerald		
540	Water Main: Homestead Ridge, Block 4 Lot 903							5th Lift		Troxler / 3430 / 38292 / 07/26/2022			Pereida, Gerald		
541	Water Main: Homestead Ridge, Block 4 Lot 903							5th Lift		Troxler / 3430 / 38292 / 07/26/2022			Pereida, Gerald		
542	Water Main: Homestead Ridge - Right STA 8+00							3rd Lift		Troxler / 3430 / 38292 / 07/26/2022			Pereida, Gerald		
543	Water Main: Homestead Ridge - Right STA 11+00							3rd Lift		Troxler / 3430 / 38292 / 07/26/2022			Pereida, Gerald		
544	Water Main: Homestead Ridge - Right STA 8+00							4th Lift		Troxler / 3430 / 38292 / 07/26/2022			Pereida, Gerald		
545	Water Main: Homestead Ridge - Right STA 11+00							4th Lift		Troxler / 3430 / 38292 / 07/26/2022			Pereida, Gerald		
546	Water Main: Homestead Ridge - Right STA 8+00							5th Lift		Troxler / 3430 / 38292 / 07/26/2022			Pereida, Gerald		
Remarks					Comments										
C: Compliant					Tests are "Direct Transmission" (Method A) unless probe depth is noted as "Backscatter". Gauge calibration data on file with the testing agency.										

Testing performed when called in.
InTEC did not observe the installation of the material.
Testing directed by the City Inspector when present.
Test results apply only to the specific locations and materials noted and may not represent any other locations or elevations.



InTEC of San Antonio
12028 Radium
San Antonio, TX 78216
Phone: 210-525-9033

Compaction Evaluation

Report Date: 10/18/2023
Test Method: ASTM D6938, Tex 115E

Client:

Pulte Homes of Texas, LP
1718 Dry Creek Way Suite 120
San Antonio, TX 78259

Project:

S212188
Corley Farms Unit 1
29.737543477901177, -98.71426779610178
Boerne, TX

Test Results															
Test #	Retest Of	Test Date	Proctor ID	Method	Soil Classification	Optimum Moisture (%)	Maximum Dry Density (pcf)	In Place Moisture (%)	In Place Dry Density (pcf)	In Place Wet Density (pcf)	Probe Depth (in)	Percent Compaction	Min Comp. (%)	Optimum Moisture Tolerance (%)	Remark
547		04/11/23	L16257		GC	12.8	119.9	10.9	117.8	130.6	6	98.2	95	-2 / 2	C
548		04/12/23	U17648		GC	12.5	119.9	11.3	124.0	138.0	6	103.4	95	-2 / 2	C
549		04/12/23	U17649		GC	10.9	125.1	10.7	124.9	138.3	6	99.8	95	-2 / 2	C
550		04/12/23	U17649		GC	10.9	125.1	10.2	124.7	137.4	6	99.7	95	-2 / 2	C
551		04/12/23	U17649		GC	10.9	125.1	9.3	124.6	136.2	6	99.6	95	-2 / 2	C
552		04/13/23	U17649		GC	10.9	125.1	10.4	123.8	136.7	6	99.0	95	-2 / 2	C
553		04/13/23	U17649		GC	10.9	125.1	9.5	124.3	136.1	6	99.4	95	-2 / 2	C
554		04/13/23	U17649		GC	10.9	125.1	9.8	123.6	135.7	6	98.8	95	-2 / 2	C
Test Information															
Test #	Test Location							Elevation	Reference		Gauge Make / Model / SN / Calibrated			Field Technician	
547	Water Main: Homestead Ridge - Right STA 11+00								5th Lift		Troxler / 3430 / 38292 / 07/26/2022			Pereida, Gerald	
548	Water Main: Homestead Ridge - Right STA 5+00								1st Lift		Troxler / 3430 / 38292 / 07/26/2022			Pereida, Gerald	
549	Water Main: Homestead Ridge, Block 6 Lot 901								1st Lift		Troxler / 3430 / 38292 / 07/26/2022			Pereida, Gerald	
550	Water Main: Homestead Ridge - Right STA 5+00								2nd Lift		Troxler / 3430 / 38292 / 07/26/2022			Pereida, Gerald	
551	Water Main: Homestead Ridge, Block 6 Lot 901								2nd Lift		Troxler / 3430 / 38292 / 07/26/2022			Pereida, Gerald	
552	Water Main: Homestead Ridge - Right STA 5+00								3rd Lift		Troxler / 3430 / 38292 / 07/26/2022			Pereida, Gerald	
553	Water Main: Homestead Ridge, Block 6 Lot 901								3rd Lift		Troxler / 3430 / 38292 / 07/26/2022			Pereida, Gerald	
554	Water Main: Homestead Ridge, Block 6 Lot 901								4th Lift		Troxler / 3430 / 38292 / 07/26/2022			Pereida, Gerald	
Remarks					Comments										
C: Compliant					Tests are "Direct Transmission" (Method A) unless probe depth is noted as "Backscatter". Gauge calibration data on file with the testing agency.										

Testing performed when called in.
InTEC did not observe the installation of the material.
Testing directed by the City Inspector when present.
Test results apply only to the specific locations and materials noted and may not represent any other locations or elevations.



InTEC of San Antonio
12028 Radium
San Antonio, TX 78216
Phone: 210-525-9033

Compaction Evaluation

Report Date: 10/18/2023
Test Method: ASTM D6938, Tex 115E

Client:

Pulte Homes of Texas, LP
1718 Dry Creek Way Suite 120
San Antonio, TX 78259

Project:

S212188
Corley Farms Unit 1
29.737543477901177, -98.71426779610178
Boerne, TX

Test Results															
Test #	Retest Of	Test Date	Proctor ID	Method	Soil Classification	Optimum Moisture (%)	Maximum Dry Density (pcf)	In Place Moisture (%)	In Place Dry Density (pcf)	In Place Wet Density (pcf)	Probe Depth (in)	Percent Compaction	Min Comp. (%)	Optimum Moisture Tolerance (%)	Remark
555		04/13/23	U17649		GC	10.9	125.1	10.3	124.2	137.0	6	99.3	95	-2 / 2	C
556		04/13/23	U17649		GC	10.9	125.1	11.2	123.3	137.1	6	98.6	95	-2 / 2	C
557		04/13/23	U17649		GC	10.9	125.1	12.0	124.9	139.9	6	99.8	95	-2 / 2	C
558		04/14/23	U17649		GC	10.9	125.1	9.6	124.0	135.9	6	99.1	95	-2 / 2	C
559		04/14/23	U17649		GC	10.9	125.1	11.2	122.8	136.6	6	98.2	95	-2 / 2	C
560		04/14/23	U17649		GC	10.9	125.1	9.1	124.6	135.9	6	99.6	95	-2 / 2	C
561		04/14/23	U17649		GC	10.9	125.1	11.2	123.8	137.7	6	99.0	95	-2 / 2	C
Test Information															
Test #	Test Location						Elevation	Reference		Gauge Make / Model / SN / Calibrated			Field Technician		
555	Water Main: Homestead Ridge, Block 6 Lot 901							5th Lift		Troxler / 3430 / 38292 / 07/26/2022			Pereida, Gerald		
556	Water Main: Homestead Ridge - Right STA 5+00							4th Lift		Troxler / 3430 / 38292 / 07/26/2022			Pereida, Gerald		
557	Water Main: Homestead Ridge - Right STA 5+00							5th Lift		Troxler / 3430 / 38292 / 07/26/2022			Pereida, Gerald		
558	Water Main: Homestead Ridge - Left STA 5+00							1st Lift		Troxler / 3430 / 38292 / 07/26/2022			Pereida, Gerald		
559	Water Main: Homestead Ridge - Left STA 8+00							1st Lift		Troxler / 3430 / 38292 / 07/26/2022			Pereida, Gerald		
560	Water Main: Homestead Ridge - Left STA 5+00							2nd Lift		Troxler / 3430 / 38292 / 07/26/2022			Pereida, Gerald		
561	Water Main: Homestead Ridge - Left STA 8+00							2nd Lift		Troxler / 3430 / 38292 / 07/26/2022			Pereida, Gerald		
Remarks					Comments										
C: Compliant					Tests are "Direct Transmission" (Method A) unless probe depth is noted as "Backscatter". Gauge calibration data on file with the testing agency.										

Testing performed when called in.
InTEC did not observe the installation of the material.
Testing directed by the City Inspector when present.
Test results apply only to the specific locations and materials noted and may not represent any other locations or elevations.



InTEC of San Antonio
12028 Radium
San Antonio, TX 78216
Phone: 210-525-9033

Compaction Evaluation

Report Date: 10/18/2023
Test Method: ASTM D6938, Tex 115E

Client:

Pulte Homes of Texas, LP
1718 Dry Creek Way Suite 120
San Antonio, TX 78259

Project:

S212188
Corley Farms Unit 1
29.737543477901177, -98.71426779610178
Boerne, TX

Test Results															
Test #	Retest Of	Test Date	Proctor ID	Method	Soil Classification	Optimum Moisture (%)	Maximum Dry Density (pcf)	In Place Moisture (%)	In Place Dry Density (pcf)	In Place Wet Density (pcf)	Probe Depth (in)	Percent Compaction	Min Comp. (%)	Optimum Moisture Tolerance (%)	Remark
155		03/01/22	U17648		GC	12.5	119.9	11.3	116.8	130.0	6	97.4	95	-2 / 2	C
156		03/01/22	U17648		GC	12.5	119.9	12.6	119.3	134.3	6	99.5	95	-2 / 2	C
159		03/01/22	U17648		GC	12.5	119.9	13.1	116.9	132.2	6	97.5	95	-2 / 2	C
160		03/01/22	U17648		GC	12.5	119.9	12.6	116.5	131.2	6	97.2	95	-2 / 2	C
163		03/02/22	U17648		GC	12.5	119.9	12.7	119.5	134.7	6	99.7	95	-2 / 2	C
164		03/02/22	U17648		GC	12.5	119.9	12.8	117.9	133.0	6	98.3	95	-2 / 2	C
171		03/03/22	U17648		GC	12.5	119.9	11.9	119.1	133.3	8	99.3	95	-2 / 2	C
172		03/03/22	U17648		GC	12.5	119.9	13.5	121.2	137.6	8	101.1	95	-2 / 2	C
Test Information															
Test #	Test Location							Elevation	Reference		Gauge Make / Model / SN / Calibrated			Field Technician	
155	Water Services: White Barn Cove, Block 3 Lot 1								1st Lift		Troxler / 3430 / 38292 / 03/30/2021			Pereida, Gerald	
156	Water Services: White Barn Cove, Block 3 Lot 4/5								1st Lift		Troxler / 3430 / 38292 / 03/30/2021			Pereida, Gerald	
159	Water Services: White Barn Cove, Block 3 Lot 1								2nd Lift		Troxler / 3430 / 38292 / 03/30/2021			Pereida, Gerald	
160	Water Services: White Barn Cove, Block 3 Lot 4/5								2nd Lift		Troxler / 3430 / 38292 / 03/30/2021			Pereida, Gerald	
163	Water Services: White Barn Cove, Block 3 Lot 1								3rd Lift		Troxler / 3430 / 38292 / 03/30/2021			Pereida, Gerald	
164	Water Services: White Barn Cove, Block 3 Lot 4/5								3rd Lift		Troxler / 3430 / 38292 / 03/30/2021			Pereida, Gerald	
171	Water Services: Rustic Barn Lane, Block 2 Lot 1								1st Lift		Troxler / 3430 / 38292 / 03/30/2021			Pereida, Gerald	
172	Water Services: Homestead Ridge, Block 5 Lot 901								1st Lift		Troxler / 3430 / 38292 / 03/30/2021			Pereida, Gerald	
Remarks					Comments										
C: Compliant					Tests are "Direct Transmission" (Method A) unless probe depth is noted as "Backscatter". Gauge calibration data on file with the testing agency.										

Testing performed when called in.
InTEC did not observe the installation of the material.
Testing directed by the City Inspector when present.
Test results apply only to the specific locations and materials noted and may not represent any other locations or elevations.



InTEC of San Antonio
12028 Radium
San Antonio, TX 78216
Phone: 210-525-9033

Compaction Evaluation

Report Date: 10/18/2023
Test Method: ASTM D6938, Tex 115E

Client:

Pulte Homes of Texas, LP
1718 Dry Creek Way Suite 120
San Antonio, TX 78259

Project:

S212188
Corley Farms Unit 1
29.737543477901177, -98.71426779610178
Boerne, TX

Test Results															
Test #	Retest Of	Test Date	Proctor ID	Method	Soil Classification	Optimum Moisture (%)	Maximum Dry Density (pcf)	In Place Moisture (%)	In Place Dry Density (pcf)	In Place Wet Density (pcf)	Probe Depth (in)	Percent Compaction	Min Comp. (%)	Optimum Moisture Tolerance (%)	Remark
182		03/03/22	U17649		GC	10.9	125.1	10.7	124.4	137.7	6	99.4	95	-2 / 2	C
183		03/03/22	U17649		GC	10.9	125.1	11.6	123.5	137.8	6	98.7	95	-2 / 2	C
186		03/04/22	U17649		GC	10.9	125.1	9.9	123.8	136.1	8	99.0	95	-2 / 2	C
187		03/04/22	U17649		GC	10.9	125.1	10.6	124.3	137.5	8	99.4	95	-2 / 2	C
189		03/04/22	U17649		GC	10.9	125.1	9.8	124.2	136.4	8	99.3	95	-2 / 2	C
203		03/10/22	U17649		GC	10.9	125.1	12.9	123.6	139.5	6	98.8	95	-2 / 2	C
204		03/10/22	U17649		GC	10.9	125.1	12.1	124.5	139.6	6	99.5	95	-2 / 2	C
205		03/10/22	U17649		GC	10.9	125.1	10.2	123.6	136.2	6	98.8	95	-2 / 2	C
Test Information															
Test #	Test Location							Elevation	Reference		Gauge Make / Model / SN / Calibrated			Field Technician	
182	Water Services: Rustic Barn Lane, Block 2 Lot 1								2nd Lift		Troxler / 3430 / 38292 / 03/30/2021			Pereida, Gerald	
183	Water Services: Homestead Ridge, Block 5 Lot 901								2nd Lift		Troxler / 3430 / 38292 / 03/30/2021			Pereida, Gerald	
186	Water Services: Homestead Ridge, Block 5 Lot 901								3rd Lift		Troxler / 3430 / 38292 / 03/30/2021			Pereida, Gerald	
187	Water Services: Rustic Barn Lane, Block 2 Lot 1								3rd Lift		Troxler / 3430 / 38292 / 03/30/2021			Pereida, Gerald	
189	Water Services: Rustic Barn Lane, Block 2 Lot 1								4th Lift		Troxler / 3430 / 38292 / 03/30/2021			Pereida, Gerald	
203	Water Services: Rustic Barn Lane, Block 1 Lot 901								1st Lift		Troxler / 3430 / 38292 / 03/30/2021			Pereida, Gerald	
204	Water Services: Homestead Ridge, Block 5 Lot 1								1st Lift		Troxler / 3430 / 38292 / 03/30/2021			Pereida, Gerald	
205	Water Services: Rustic Barn Lane, Block 1 Lot 901								2nd Lift		Troxler / 3430 / 38292 / 03/30/2021			Pereida, Gerald	
Remarks					Comments										
C: Compliant					Tests are "Direct Transmission" (Method A) unless probe depth is noted as "Backscatter". Gauge calibration data on file with the testing agency.										

Testing performed when called in.
InTEC did not observe the installation of the material.
Testing directed by the City Inspector when present.
Test results apply only to the specific locations and materials noted and may not represent any other locations or elevations.



InTEC of San Antonio
12028 Radium
San Antonio, TX 78216
Phone: 210-525-9033

Compaction Evaluation

Report Date: 10/18/2023
Test Method: ASTM D6938, Tex 115E

Client:

Pulte Homes of Texas, LP
1718 Dry Creek Way Suite 120
San Antonio, TX 78259

Project:

S212188
Corley Farms Unit 1
29.737543477901177, -98.71426779610178
Boerne, TX

Test Results															
Test #	Retest Of	Test Date	Proctor ID	Method	Soil Classification	Optimum Moisture (%)	Maximum Dry Density (pcf)	In Place Moisture (%)	In Place Dry Density (pcf)	In Place Wet Density (pcf)	Probe Depth (in)	Percent Compaction	Min Comp. (%)	Optimum Moisture Tolerance (%)	Remark
206		03/10/22	U17649		GC	10.9	125.1	10.4	124.6	137.6	6	99.6	95	-2 / 2	C
207		03/11/22	U17649		GC	10.9	125.1	10.8	124.8	138.3	6	99.8	95	-2 / 2	C
208		03/11/22	U17649		GC	10.9	125.1	11.5	126.3	140.8	6	101.0	95	-2 / 2	C
Test Information															
Test #	Test Location							Elevation	Reference		Gauge Make / Model / SN / Calibrated			Field Technician	
206	Water Services: Homestead Ridge, Block 5 Lot 1								2nd Lift		Troxler / 3430 / 38292 / 03/30/2021			Pereida, Gerald	
207	Water Services: Rustic Barn Lane, Block 1 Lot 901								3rd Lift		Troxler / 3430 / 38292 / 03/30/2021			Pereida, Gerald	
208	Water Services: Homestead Ridge, Block 5 Lot 1								3rd Lift		Troxler / 3430 / 38292 / 03/30/2021			Pereida, Gerald	
Remarks					Comments										
C: Compliant					Tests are "Direct Transmission" (Method A) unless probe depth is noted as "Backscatter". Gauge calibration data on file with the testing agency.										

Testing performed when called in.
InTEC did not observe the installation of the material.
Testing directed by the City Inspector when present.
Test results apply only to the specific locations and materials noted and may not represent any other locations or elevations.