



Professional Service Industries, Inc.  
Three Burwood Lane  
San Antonio, TX 78216  
Texas Firm Registration No. F-03307  
Phone: (210) 342-9377  
Fax: (210) 342-9401

Report No: SDFR:03113664-114

Issue No: 1

These test results apply only to the specific locations and materials noted and may not represent any other locations or elevations. This report may not be reproduced, except in full, without written permission by Professional Service Industries, Inc. If a non-compliance appears on this report, to the extent that the reported non-compliance impacts the project, the resolution is outside the PSI scope of engagement.

Approved Signatory: Ernesto Gomez (Project Manager)  
Date of Issue: 10/24/2022

## Summary Daily Field Report

**Client:** ASHTON WOODS  
17319 SAN PEDRO  
SUITE 140  
SAN ANTONIO, TX 78232

**CC:**  
COLBY OLGETREE

**Project:** JUNGMAN UNIT 1  
SAN ANTONIO, TX

**Date:** 10/22/2022

**WEATHER:** Clear  
**TEMPERATURE RANGE:** 70 °F TO 75 °F  
**PSI REPRESENTATIVE:** Benjamin Urbina

### TYPE OF INSPECTION BEING PERFORMED

#### SOILS

- ☐ FOUNDATIONS  
☐ CONTROLLED FILL (COMPACTION)  
☐

#### ASPHALT

- ☐ BATCH PLANT  
☐ PLACEMENT (JOB SITE)  
☐

#### CONCRETE

- ☐ BATCH PLANT  
☐ PLACEMENT (JOB SITE)  
☒ SPECIMEN TRANSPORT  
☒ 03113664-113, C1

#### OTHER

- ☐  
☐  
☐

### BRIEF RESUME OF WORK ACCOMPLISHED THIS DATE:

As requested, a representative of PSI reported to the above referenced project site to retrieve 1 set of 5 cylinders cast by PSI on 10/22/2022 which were transported back to the PSI laboratory for further curing and compressive strength testing.



Professional Service Industries, Inc.  
Three Burwood Lane  
San Antonio, TX 78216  
Texas Firm Registration No. F-03307  
Phone: (210) 342-9377  
Fax: (210) 342-9401

Report No: SDFR:03113664-117

Issue No: 1

These test results apply only to the specific locations and materials noted and may not represent any other locations or elevations. This report may not be reproduced, except in full, without written permission by Professional Service Industries, Inc. If a non-compliance appears on this report, to the extent that the reported non-compliance impacts the project, the resolution is outside the PSI scope of engagement.

Approved Signatory: Ernesto Gomez (Project Manager)  
Date of Issue: 10/26/2022

## Summary Daily Field Report

**Client:** ASHTON WOODS  
17319 SAN PEDRO  
SUITE 140  
SAN ANTONIO, TX 78232

**CC:**  
COLBY OLGETREE

**Project:** JUNGMAN UNIT 1  
SAN ANTONIO, TX

**Date:** 10/26/2022

**WEATHER:** Clear  
**TEMPERATURE RANGE:** 76 °F TO 77 °F  
**PSI REPRESENTATIVE:** Benjamin Urbina

### TYPE OF INSPECTION BEING PERFORMED

#### SOILS

- ☐ FOUNDATIONS  
☐ CONTROLLED FILL (COMPACTION)  
☐

#### ASPHALT

- ☐ BATCH PLANT  
☐ PLACEMENT (JOB SITE)  
☐

#### CONCRETE

- ☐ BATCH PLANT  
☐ PLACEMENT (JOB SITE)  
☒ SPECIMEN TRANSPORT  
☒ 03113664-116, C1

#### OTHER

- ☐  
☐  
☐

### BRIEF RESUME OF WORK ACCOMPLISHED THIS DATE:

As requested, a representative of PSI reported to the above referenced project site to retrieve 1 set of 5 cylinders cast by PSI on 10/25/2022 which were transported back to the PSI laboratory for further curing and compressive strength testing.



Professional Service Industries, Inc.  
Three Burwood Lane  
San Antonio, TX 78216  
Texas Firm Registration No. F-03307  
Phone: (210) 342-9377  
Fax: (210) 342-9401

Report No: SDFR:03113664-121

Issue No: 1

These test results apply only to the specific locations and materials noted and may not represent any other locations or elevations. This report may not be reproduced, except in full, without written permission by Professional Service Industries, Inc. If a non-compliance appears on this report, to the extent that the reported non-compliance impacts the project, the resolution is outside the PSI scope of engagement.

Approved Signatory: Ernesto Gomez (Project Manager)  
Date of Issue: 11/8/2022

## Summary Daily Field Report

**Client:** ASHTON WOODS  
17319 SAN PEDRO  
SUITE 140  
SAN ANTONIO, TX 78232

**CC:**  
COLBY OLGETREE

**Project:** JUNGMAN UNIT 1  
SAN ANTONIO, TX

**Date:** 11/5/2022

**WEATHER:** Clear  
**TEMPERATURE RANGE:** 70 °F TO 72 °F  
**PSI REPRESENTATIVE:** Benjamin Urbina

### TYPE OF INSPECTION BEING PERFORMED

#### SOILS

- ☐ FOUNDATIONS  
☐ CONTROLLED FILL (COMPACTION)  
☐

#### ASPHALT

- ☐ BATCH PLANT  
☐ PLACEMENT (JOB SITE)  
☐

#### CONCRETE

- ☐ BATCH PLANT  
☐ PLACEMENT (JOB SITE)  
☒ SPECIMEN TRANSPORT  
☒ 03113664-120, C1

#### OTHER

- ☐  
☐  
☐

### BRIEF RESUME OF WORK ACCOMPLISHED THIS DATE:

As requested, a representative of PSI reported to the above referenced project site to retrieve 1 set of 5 cylinders cast by PSI on 11/04/2022 which were transported back to the PSI laboratory for further curing and compressive strength testing.



Professional Service Industries, Inc.  
Three Burwood Lane  
San Antonio, TX 78216  
Texas Firm Registration No. F-03307  
Phone: (210) 342-9377  
Fax: (210) 342-9401

Report No: SDFR:03113664-126

Issue No: 1

These test results apply only to the specific locations and materials noted and may not represent any other locations or elevations. This report may not be reproduced, except in full, without written permission by Professional Service Industries, Inc. If a non-compliance appears on this report, to the extent that the reported non-compliance impacts the project, the resolution is outside the PSI scope of engagement.

Approved Signatory: Ernesto Gomez (Project Manager)  
Date of Issue: 11/15/2022

## Summary Daily Field Report

**Client:** ASHTON WOODS  
17319 SAN PEDRO  
SUITE 140  
SAN ANTONIO, TX 78232

**CC:**  
COLBY OLGETREE

**Project:** JUNGMAN UNIT 1  
SAN ANTONIO, TX

**Date:** 11/11/2022

**WEATHER:** Clear  
**TEMPERATURE RANGE:** 74 °F TO 76 °F  
**PSI REPRESENTATIVE:** Benjamin Urbina

### TYPE OF INSPECTION BEING PERFORMED

#### SOILS

- ☐ FOUNDATIONS  
☐ CONTROLLED FILL (COMPACTION)  
☐

#### ASPHALT

- ☐ BATCH PLANT  
☐ PLACEMENT (JOB SITE)  
☐

#### CONCRETE

- ☐ BATCH PLANT  
☐ PLACEMENT (JOB SITE)  
☐ SPECIMEN TRANSPORT  
☐

#### OTHER

- ☐  
☐  
☐

### BRIEF RESUME OF WORK ACCOMPLISHED THIS DATE:

As requested and scheduled, a Professional Service Industries, Inc. representative reported to the referenced project to obtain a sample of the material identified below for laboratory testing. The test results will be reported on a separate report.

Material Description: Tan Crushed Limestone (ACE Aggregates)  
Application: Roadway Base  
Test Method: Tex-113E - Proctor, C136 - Sieve Analysis, D1140 - #200 Wash, D4318 - Atterberg (PI)  
Lab Reference No.: 857

If there are any questions concerning this report, please contact our office at your earliest convenience.

Respectfully submitted,  
Intertek-PSI



Professional Service Industries, Inc.  
Three Burwood Lane  
San Antonio, TX 78216  
Texas Firm Registration No. F-03307  
Phone: (210) 342-9377  
Fax: (210) 342-9401

Report No: SDFR:03113664-130

Issue No: 1

These test results apply only to the specific locations and materials noted and may not represent any other locations or elevations. This report may not be reproduced, except in full, without written permission by Professional Service Industries, Inc. If a non-compliance appears on this report, to the extent that the reported non-compliance impacts the project, the resolution is outside the PSI scope of engagement.

Approved Signatory: Ernesto Gomez (Project Manager)  
Date of Issue: 11/23/2022

## Summary Daily Field Report

**Client:** ASHTON WOODS  
17319 SAN PEDRO  
SUITE 140  
SAN ANTONIO, TX 78232

**CC:**  
COLBY OLGETREE

**Project:** JUNGMAN UNIT 1  
SAN ANTONIO, TX

**Date:** 11/22/2022

**WEATHER:** Lite Rain  
**TEMPERATURE RANGE:** 55 °F TO 60 °F  
**PSI REPRESENTATIVE:** Roberto Cardenas

### TYPE OF INSPECTION BEING PERFORMED

#### SOILS

- ☐ FOUNDATIONS  
☐ CONTROLLED FILL (COMPACTION)  
☐

#### ASPHALT

- ☐ BATCH PLANT  
☐ PLACEMENT (JOB SITE)  
☐

#### CONCRETE

- ☐ BATCH PLANT  
☐ PLACEMENT (JOB SITE)  
☒ SPECIMEN TRANSPORT  
☒ 03113664-129, C1

#### OTHER

- ☐  
☐  
☐

### BRIEF RESUME OF WORK ACCOMPLISHED THIS DATE:

A PSI representative arrived at the referenced project to pick up 1 sets of 5 compressive strength test specimens molded on 11/18/2022 and returned them to the laboratory for further processing and testing.

Respectfully Submitted,  
Intertek-PSI, Inc



Professional Service Industries, Inc.  
Three Burwood Lane  
San Antonio, TX 78216  
Texas Firm Registration No. F-03307  
Phone: (210) 342-9377  
Fax: (210) 342-9401

Report No: SDFR:03113664-135

Issue No: 1

These test results apply only to the specific locations and materials noted and may not represent any other locations or elevations. This report may not be reproduced, except in full, without written permission by Professional Service Industries, Inc. If a non-compliance appears on this report, to the extent that the reported non-compliance impacts the project, the resolution is outside the PSI scope of engagement.

Approved Signatory: Ernesto Gomez (Project Manager)  
Date of Issue: 12/8/2022

## Summary Daily Field Report

**Client:** ASHTON WOODS  
17319 SAN PEDRO  
SUITE 140  
SAN ANTONIO, TX 78232

**CC:**  
COLBY OLGETREE

**Project:** JUNGMAN UNIT 1  
SAN ANTONIO, TX

**Date:** 12/1/2022

**WEATHER:** Clear  
**TEMPERATURE RANGE:** 64 °F TO 66 °F  
**PSI REPRESENTATIVE:** Benjamin Urbina

### TYPE OF INSPECTION BEING PERFORMED

#### SOILS

- ☐ FOUNDATIONS  
☐ CONTROLLED FILL (COMPACTION)  
☐

#### ASPHALT

- ☐ BATCH PLANT  
☐ PLACEMENT (JOB SITE)  
☐

#### CONCRETE

- ☐ BATCH PLANT  
☐ PLACEMENT (JOB SITE)  
☐ SPECIMEN TRANSPORT  
☐

#### OTHER

- ☐  
☐  
☐

### BRIEF RESUME OF WORK ACCOMPLISHED THIS DATE:

As requested and scheduled, a Professional Service Industries, Inc. representative reported to the referenced project to obtain a sample of the material identified below for laboratory testing. The test results will be reported on a separate report.

Material Description: Tan Crushed Limestone (Vulcan Materials)  
Application: Roadway Base  
Test Method: Tex-113E - Proctor, C136 - Sieve Analysis, D1140 - #200 Wash, D4318 - Atterberg (PI)  
Lab Reference No.: 874

If there are any questions concerning this report, please contact our office at your earliest convenience.

Respectfully submitted,  
Intertek-PSI



Professional Service Industries, Inc.  
Three Burwood Lane  
San Antonio, TX 78216  
Texas Firm Registration No. F-03307  
Phone: (210) 342-9377  
Fax: (210) 342-9401

Report No: SDFR:03113664-136

Issue No: 1

These test results apply only to the specific locations and materials noted and may not represent any other locations or elevations. This report may not be reproduced, except in full, without written permission by Professional Service Industries, Inc. If a non-compliance appears on this report, to the extent that the reported non-compliance impacts the project, the resolution is outside the PSI scope of engagement.

Approved Signatory: Ernesto Gomez (Project Manager)  
Date of Issue: 12/8/2022

## Summary Daily Field Report

**Client:** ASHTON WOODS  
17319 SAN PEDRO  
SUITE 140  
SAN ANTONIO, TX 78232

**CC:**  
COLBY OLGETREE

**Project:** JUNGMAN UNIT 1  
SAN ANTONIO, TX

**Date:** 12/2/2022

**WEATHER:** Cloudy  
**TEMPERATURE RANGE:** 62 °F TO 64 °F  
**PSI REPRESENTATIVE:** Benjamin Urbina

### TYPE OF INSPECTION BEING PERFORMED

#### SOILS

- ☐ FOUNDATIONS  
☐ CONTROLLED FILL (COMPACTION)  
☐

#### ASPHALT

- ☐ BATCH PLANT  
☐ PLACEMENT (JOB SITE)  
☐

#### CONCRETE

- ☐ BATCH PLANT  
☐ PLACEMENT (JOB SITE)  
☒ SPECIMEN TRANSPORT  
☐

#### OTHER

- ☐  
☐  
☐

### BRIEF RESUME OF WORK ACCOMPLISHED THIS DATE:

As requested, a representative of PSI reported to the above referenced project site to retrieve 1 set of 5 cylinders cast by PSI on 12-01-2022 which were transported back to the PSI laboratory for further curing and compressive strength testing.



Professional Service Industries, Inc.  
Three Burwood Lane  
San Antonio, TX 78216  
Texas Firm Registration No. F-03307  
Phone: (210) 342-9377  
Fax: (210) 342-9401

Report No: SDFR:03113664-136

Issue No: 1

These test results apply only to the specific locations and materials noted and may not represent any other locations or elevations. This report may not be reproduced, except in full, without written permission by Professional Service Industries, Inc. If a non-compliance appears on this report, to the extent that the reported non-compliance impacts the project, the resolution is outside the PSI scope of engagement.

Approved Signatory: Ernesto Gomez (Project Manager)  
Date of Issue: 12/8/2022

## Summary Daily Field Report

**Client:** ASHTON WOODS  
17319 SAN PEDRO  
SUITE 140  
SAN ANTONIO, TX 78232

**CC:** COLBY OLGETREE

**Project:** JUNGMAN UNIT 1  
SAN ANTONIO, TX

**Date:** 12/2/2022

**WEATHER:** Cloudy  
**TEMPERATURE RANGE:** 62 °F TO 64 °F  
**PSI REPRESENTATIVE:** Benjamin Urbina

### TYPE OF INSPECTION BEING PERFORMED

#### SOILS

- ☐ FOUNDATIONS  
☐ CONTROLLED FILL (COMPACTION)  
☐

#### ASPHALT

- ☐ BATCH PLANT  
☐ PLACEMENT (JOB SITE)  
☐

#### CONCRETE

- ☐ BATCH PLANT  
☐ PLACEMENT (JOB SITE)  
☐ SPECIMEN TRANSPORT  
☐

#### OTHER

- ☒ SOIL SAMPLE PICK UP  
☐  
☐

### BRIEF RESUME OF WORK ACCOMPLISHED THIS DATE:

As requested and scheduled, a Professional Service Industries, Inc. representative reported to the referenced project to obtain a sample of the material identified below for laboratory testing. The test results will be reported on a separate report.

Material Description: Brown Clayey Sand (Hennersby way Club house drive in way)  
Application: Subgrade (Lime Stabilized)  
Test Method: Tex-114-E - TxDot Proctor, C136 - Sieve Analysis, D1140 - #200 Wash, D4318 - Atterberg (PI)  
Lab Reference No.: 872

If there are any questions concerning this report, please contact our office at your earliest convenience.

Respectfully submitted,  
Intertek-PSI





Professional Service Industries, Inc.  
Three Burwood Lane  
San Antonio, TX 78216  
Texas Firm Registration No. F-03307  
Phone: (210) 342-9377  
Fax: (210) 342-9401

Report No: SDFR:03113664-139

Issue No: 1

These test results apply only to the specific locations and materials noted and may not represent any other locations or elevations. This report may not be reproduced, except in full, without written permission by Professional Service Industries, Inc. If a non-compliance appears on this report, to the extent that the reported non-compliance impacts the project, the resolution is outside the PSI scope of engagement.

Approved Signatory: Ernesto Gomez (Project Manager)  
Date of Issue: 12/12/2022

## Summary Daily Field Report

**Client:** ASHTON WOODS  
17319 SAN PEDRO  
SUITE 140  
SAN ANTONIO, TX 78232

**CC:**  
COLBY OLGETREE

**Project:** JUNGMAN UNIT 1  
SAN ANTONIO, TX

**Date:** 12/8/2022

**WEATHER:** Cloudy  
**TEMPERATURE RANGE:** 67 °F TO 68 °F  
**PSI REPRESENTATIVE:** Benjamin Urbina

### TYPE OF INSPECTION BEING PERFORMED

#### SOILS

- ☐ FOUNDATIONS  
☐ CONTROLLED FILL (COMPACTION)  
☐

#### ASPHALT

- ☐ BATCH PLANT  
☐ PLACEMENT (JOB SITE)  
☐

#### CONCRETE

- ☐ BATCH PLANT  
☐ PLACEMENT (JOB SITE)  
☐ SPECIMEN TRANSPORT  
☐

#### OTHER

- ☒ SOIL SAMPLE PICK UP  
☐  
☐

### BRIEF RESUME OF WORK ACCOMPLISHED THIS DATE:

As requested and scheduled, a Professional Service Industries, Inc. representative reported to the referenced project to obtain a sample of the material identified below for laboratory testing. The test results will be reported on a separate report.

Material Description: #2 sample Brown Clayey Sand ( Club house drive in way)  
Application: Subgrade (Lime Stabilized)  
Test Method: Tex-114-E - TxDot Proctor, C136 - Sieve Analysis, D1140 - #200 Wash, D4318 - Atterberg (PI)  
Lab Reference No.: 882

If there are any questions concerning this report, please contact our office at your earliest convenience.

Respectfully submitted,  
Intertek-PSI



Professional Service Industries, Inc.  
Three Burwood Lane  
San Antonio, TX 78216  
Texas Firm Registration No. F-03307  
Phone: (210) 342-9377  
Fax: (210) 342-9401

Report No: SDFR:03113664-139

Issue No: 1

These test results apply only to the specific locations and materials noted and may not represent any other locations or elevations. This report may not be reproduced, except in full, without written permission by Professional Service Industries, Inc. If a non-compliance appears on this report, to the extent that the reported non-compliance impacts the project, the resolution is outside the PSI scope of engagement.

Approved Signatory: Ernesto Gomez (Project Manager)  
Date of Issue: 12/12/2022

## Summary Daily Field Report

**Client:** ASHTON WOODS  
17319 SAN PEDRO  
SUITE 140  
SAN ANTONIO, TX 78232

**CC:** COLBY OLGETREE

**Project:** JUNGMAN UNIT 1  
SAN ANTONIO, TX

**Date:** 12/8/2022

**WEATHER:** Clear  
**TEMPERATURE RANGE:** 67 °F TO 69 °F  
**PSI REPRESENTATIVE:** Benjamin Urbina

### TYPE OF INSPECTION BEING PERFORMED

#### SOILS

- ☐ FOUNDATIONS  
☐ CONTROLLED FILL (COMPACTION)  
☐

#### ASPHALT

- ☐ BATCH PLANT  
☐ PLACEMENT (JOB SITE)  
☐

#### CONCRETE

- ☐ BATCH PLANT  
☐ PLACEMENT (JOB SITE)  
☒ SPECIMEN TRANSPORT  
☐

#### OTHER

- ☐  
☐  
☐

### BRIEF RESUME OF WORK ACCOMPLISHED THIS DATE:

As requested, a representative of PSI reported to the above referenced project site to retrieve 1 set of 5 cylinders cast by PSI on 12/07/2022 which were transported back to the PSI laboratory for further curing and compressive strength testing.



Professional Service Industries, Inc.  
Three Burwood Lane  
San Antonio, TX 78216  
Texas Firm Registration No. F-03307  
Phone: (210) 342-9377  
Fax: (210) 342-9401

Report No: SDFR:03113664-142

Issue No: 1

These test results apply only to the specific locations and materials noted and may not represent any other locations or elevations. This report may not be reproduced, except in full, without written permission by Professional Service Industries, Inc. If a non-compliance appears on this report, to the extent that the reported non-compliance impacts the project, the resolution is outside the PSI scope of engagement.

Approved Signatory: Ernesto Gomez (Project Manager)  
Date of Issue: 12/15/2022

## Summary Daily Field Report

**Client:** ASHTON WOODS  
17319 SAN PEDRO  
SUITE 140  
SAN ANTONIO, TX 78232

**CC:** COLBY OLGETREE

**Project:** JUNGMAN UNIT 1  
SAN ANTONIO, TX

**Date:** 12/12/2022

**WEATHER:** Cloudy  
**TEMPERATURE RANGE:** 70 °F TO 72 °F  
**PSI REPRESENTATIVE:** Benjamin Urbina

### TYPE OF INSPECTION BEING PERFORMED

#### SOILS

- ☐ FOUNDATIONS  
☐ CONTROLLED FILL (COMPACTION)  
☐

#### ASPHALT

- ☐ BATCH PLANT  
☐ PLACEMENT (JOB SITE)  
☐

#### CONCRETE

- ☐ BATCH PLANT  
☐ PLACEMENT (JOB SITE)  
☒ SPECIMEN TRANSPORT  
☐

#### OTHER

- ☐  
☐  
☐

### BRIEF RESUME OF WORK ACCOMPLISHED THIS DATE:

As requested, a representative of PSI reported to the above referenced project site to retrieve 1 set of 5 cylinders cast by PSI on 12/9/2022 which were transported back to the PSI laboratory for further curing and compressive strength testing.



Professional Service Industries, Inc.  
Three Burwood Lane  
San Antonio, TX 78216  
Texas Firm Registration No. F-03307  
Phone: (210) 342-9377  
Fax: (210) 342-9401

Report No: SDFR:03113664-144

Issue No: 1

These test results apply only to the specific locations and materials noted and may not represent any other locations or elevations. This report may not be reproduced, except in full, without written permission by Professional Service Industries, Inc. If a non-compliance appears on this report, to the extent that the reported non-compliance impacts the project, the resolution is outside the PSI scope of engagement.

Approved Signatory: Ernesto Gomez (Project Manager)  
Date of Issue: 12/16/2022

## Summary Daily Field Report

**Client:** ASHTON WOODS  
17319 SAN PEDRO  
SUITE 140  
SAN ANTONIO, TX 78232

**CC:**  
COLBY OLGETREE

**Project:** JUNGMAN UNIT 1  
SAN ANTONIO, TX

**Date:** 12/13/2022

**WEATHER:** Cloudy  
**TEMPERATURE RANGE:** 62 °F TO 63 °F  
**PSI REPRESENTATIVE:** Benjamin Urbina

### TYPE OF INSPECTION BEING PERFORMED

#### SOILS

- ☐ FOUNDATIONS  
☐ CONTROLLED FILL (COMPACTION)  
☐

#### ASPHALT

- ☐ BATCH PLANT  
☐ PLACEMENT (JOB SITE)  
☐

#### CONCRETE

- ☐ BATCH PLANT  
☐ PLACEMENT (JOB SITE)  
☐ SPECIMEN TRANSPORT  
☐

#### OTHER

- ☒ SOIL SAMPLE PICK UP  
☐  
☐

### BRIEF RESUME OF WORK ACCOMPLISHED THIS DATE:

As requested and scheduled, a Professional Service Industries, Inc. representative reported to the referenced project to obtain a 2nd time sample of the material identified below for laboratory testing. The test results will be reported on a separate report.

Material Description: Brown Clayey Sand (Hennersby way Club house drive in way)  
Application: Subgrade (Lime Stabilized)  
Test Method: Tex-114-E - TxDot Proctor, C136 - Sieve Analysis, D1140 - #200 Wash, D4318 - Atterberg (PI)  
Lab Reference No.: 882

If there are any questions concerning this report, please contact our office at your earliest convenience.

Respectfully submitted,  
Intertek-PSI



Professional Service Industries, Inc.  
Three Burwood Lane  
San Antonio, TX 78216  
Texas Firm Registration No. F-03307  
Phone: (210) 342-9377  
Fax: (210) 342-9401

Report No: SDFR:03113664-146

Issue No: 1

These test results apply only to the specific locations and materials noted and may not represent any other locations or elevations. This report may not be reproduced, except in full, without written permission by Professional Service Industries, Inc. If a non-compliance appears on this report, to the extent that the reported non-compliance impacts the project, the resolution is outside the PSI scope of engagement.

Approved Signatory: Ernesto Gomez (Project Manager)  
Date of Issue: 12/16/2022

## Summary Daily Field Report

**Client:** ASHTON WOODS  
17319 SAN PEDRO  
SUITE 140  
SAN ANTONIO, TX 78232

**CC:** COLBY OLGETREE

**Project:** JUNGMAN UNIT 1  
SAN ANTONIO, TX

**Date:** 12/15/2022

**WEATHER:** Cloudy  
**TEMPERATURE RANGE:** 72 °F TO 73 °F  
**PSI REPRESENTATIVE:** Benjamin Urbina

### TYPE OF INSPECTION BEING PERFORMED

#### SOILS

- ☐ FOUNDATIONS  
☐ CONTROLLED FILL (COMPACTION)  
☐

#### ASPHALT

- ☐ BATCH PLANT  
☐ PLACEMENT (JOB SITE)  
☐

#### CONCRETE

- ☐ BATCH PLANT  
☐ PLACEMENT (JOB SITE)  
☒ SPECIMEN TRANSPORT  
☒ 03113664-145, C1

#### OTHER

- ☐  
☐  
☐

### BRIEF RESUME OF WORK ACCOMPLISHED THIS DATE:

As requested, a representative of PSI reported to the above referenced project site to retrieve 1 set of 5 cylinders cast by PSI on 12/14/2022 which were transported back to the PSI laboratory for further curing and compressive strength testing.



Professional Service Industries, Inc.  
Three Burwood Lane  
San Antonio, TX 78216  
Texas Firm Registration No. F-03307  
Phone: (210) 342-9377  
Fax: (210) 342-9401

Report No: SDFR:03113664-151

Issue No: 1

These test results apply only to the specific locations and materials noted and may not represent any other locations or elevations. This report may not be reproduced, except in full, without written permission by Professional Service Industries, Inc. If a non-compliance appears on this report, to the extent that the reported non-compliance impacts the project, the resolution is outside the PSI scope of engagement.

Approved Signatory: Ernesto Gomez (Project Manager)  
Date of Issue: 12/28/2022

## Summary Daily Field Report

**Client:** ASHTON WOODS  
17319 SAN PEDRO  
SUITE 140  
SAN ANTONIO, TX 78232

**CC:**  
COLBY OLGETREE

**Project:** JUNGMAN UNIT 1  
SAN ANTONIO, TX

**Date:** 12/27/2022

**WEATHER:** Cloudy  
**TEMPERATURE RANGE:** 50 °F TO 51 °F  
**PSI REPRESENTATIVE:** Benjamin Urbina

### TYPE OF INSPECTION BEING PERFORMED

#### SOILS

- ☐ FOUNDATIONS  
☐ CONTROLLED FILL (COMPACTION)  
☐

#### ASPHALT

- ☐ BATCH PLANT  
☐ PLACEMENT (JOB SITE)  
☐

#### CONCRETE

- ☐ BATCH PLANT  
☐ PLACEMENT (JOB SITE)  
☒ SPECIMEN TRANSPORT  
☒ 03113664-150, C1

#### OTHER

- ☐  
☐  
☐

### BRIEF RESUME OF WORK ACCOMPLISHED THIS DATE:

As requested, a representative of PSI reported to the above referenced project site to retrieve 1 set of 5 cylinders cast by PSI on 12/22/2022 which were transported back to the PSI laboratory for further curing and compressive strength testing.



Professional Service Industries, Inc.  
Three Burwood Lane  
San Antonio, TX 78216  
Texas Firm Registration No. F-03307  
Phone: (210) 342-9377  
Fax: (210) 342-9401

Report No: SDFR:03113664-155

Issue No: 1

These test results apply only to the specific locations and materials noted and may not represent any other locations or elevations. This report may not be reproduced, except in full, without written permission by Professional Service Industries, Inc. If a non-compliance appears on this report, to the extent that the reported non-compliance impacts the project, the resolution is outside the PSI scope of engagement.

Approved Signatory: Ernesto Gomez (Project Manager)  
Date of Issue: 1/10/2023

## Summary Daily Field Report

**Client:** ASHTON WOODS  
17319 SAN PEDRO  
SUITE 140  
SAN ANTONIO, TX 78232

**CC:**  
COLBY OLGETREE

**Project:** JUNGMAN UNIT 1  
SAN ANTONIO, TX

**Date:** 1/5/2023

**WEATHER:** Clear  
**TEMPERATURE RANGE:** 50 °F TO 51 °F  
**PSI REPRESENTATIVE:** Benjamin Urbina

### TYPE OF INSPECTION BEING PERFORMED

#### SOILS

- ☐ FOUNDATIONS  
☐ CONTROLLED FILL (COMPACTION)  
☐

#### ASPHALT

- ☐ BATCH PLANT  
☐ PLACEMENT (JOB SITE)  
☐

#### CONCRETE

- ☐ BATCH PLANT  
☐ PLACEMENT (JOB SITE)  
☒ SPECIMEN TRANSPORT  
☒ 03113664-154, C1

#### OTHER

- ☐  
☐  
☐

### BRIEF RESUME OF WORK ACCOMPLISHED THIS DATE:

As requested, a representative of PSI reported to the above referenced project site to retrieve 1 set of 5 cylinders cast by PSI on 01/04/2023 which were transported back to the PSI laboratory for further curing and compressive strength testing.



Professional Service Industries, Inc.  
Three Burwood Lane  
San Antonio, TX 78216  
Texas Firm Registration No. F-03307  
Phone: (210) 342-9377  
Fax: (210) 342-9401

Report No: SDFR:03113664-159

Issue No: 1

These test results apply only to the specific locations and materials noted and may not represent any other locations or elevations. This report may not be reproduced, except in full, without written permission by Professional Service Industries, Inc. If a non-compliance appears on this report, to the extent that the reported non-compliance impacts the project, the resolution is outside the PSI scope of engagement.

Approved Signatory: Ernesto Gomez (Project Manager)  
Date of Issue: 1/12/2023

## Summary Daily Field Report

**Client:** ASHTON WOODS  
17319 SAN PEDRO  
SUITE 140  
SAN ANTONIO, TX 78232

**CC:**  
COLBY OLGETREE

**Project:** JUNGMAN UNIT 1  
SAN ANTONIO, TX

**Date:** 1/11/2023

**WEATHER:** Cloudy  
**TEMPERATURE RANGE:** 65 °F TO 66 °F  
**PSI REPRESENTATIVE:** Benjamin Urbina

### TYPE OF INSPECTION BEING PERFORMED

#### SOILS

- ☐ FOUNDATIONS  
☐ CONTROLLED FILL (COMPACTION)  
☐

#### ASPHALT

- ☐ BATCH PLANT  
☐ PLACEMENT (JOB SITE)  
☐

#### CONCRETE

- ☐ BATCH PLANT  
☐ PLACEMENT (JOB SITE)  
☒ SPECIMEN TRANSPORT  
☒ 03113664-158, C1

#### OTHER

- ☐  
☐  
☐

### BRIEF RESUME OF WORK ACCOMPLISHED THIS DATE:

As requested, a representative of PSI reported to the above referenced project site to retrieve 1 set of 5 cylinders cast by PSI on 01/10/2023 which were transported back to the PSI laboratory for further curing and compressive strength testing.





Professional Service Industries, Inc.  
Three Burwood Lane  
San Antonio, TX 78216  
Texas Firm Registration No. F-03307  
Phone: (210) 342-9377  
Fax: (210) 342-9401

Report No: SDFR:03113664-163

Issue No: 1

These test results apply only to the specific locations and materials noted and may not represent any other locations or elevations. This report may not be reproduced, except in full, without written permission by Professional Service Industries, Inc. If a non-compliance appears on this report, to the extent that the reported non-compliance impacts the project, the resolution is outside the PSI scope of engagement.

Approved Signatory: Ernesto Gomez (Project Manager)  
Date of Issue: 1/20/2023

## Summary Daily Field Report

**Client:** ASHTON WOODS  
17319 SAN PEDRO  
SUITE 140  
SAN ANTONIO, TX 78232

**CC:**  
COLBY OLGETREE

**Project:** JUNGMAN UNIT 1  
SAN ANTONIO, TX

**Date:** 1/16/2023

**WEATHER:** Partly Cloudy  
**TEMPERATURE RANGE:** 65 °F TO 70 °F  
**PSI REPRESENTATIVE:** Joshua Smith

### TYPE OF INSPECTION BEING PERFORMED

#### SOILS

- ☐ FOUNDATIONS  
☐ CONTROLLED FILL (COMPACTION)  
☐

#### ASPHALT

- ☐ BATCH PLANT  
☐ PLACEMENT (JOB SITE)  
☐

#### CONCRETE

- ☐ BATCH PLANT  
☐ PLACEMENT (JOB SITE)  
☒ SPECIMEN TRANSPORT  
☒ 03113664-162, C!

#### OTHER

- ☐  
☐  
☐

### BRIEF RESUME OF WORK ACCOMPLISHED THIS DATE:

A PSI representative arrived at the referenced project to pick up 1 set of 5 compressive strength test specimens molded on 01/13/2023 and returned them to the laboratory for further processing and testing.

Respectfully Submitted,  
Intertek-PSI, Inc



Professional Service Industries, Inc.  
Three Burwood Lane  
San Antonio, TX 78216  
Texas Firm Registration No. F-03307  
Phone: (210) 342-9377  
Fax: (210) 342-9401

Report No: SDFR:03113664-166

Issue No: 1

These test results apply only to the specific locations and materials noted and may not represent any other locations or elevations. This report may not be reproduced, except in full, without written permission by Professional Service Industries, Inc. If a non-compliance appears on this report, to the extent that the reported non-compliance impacts the project, the resolution is outside the PSI scope of engagement.

Approved Signatory: Ernesto Gomez (Project Manager)  
Date of Issue: 1/23/2023

## Summary Daily Field Report

**Client:** ASHTON WOODS  
17319 SAN PEDRO  
SUITE 140  
SAN ANTONIO, TX 78232

**CC:**  
COLBY OLGETREE

**Project:** JUNGMAN UNIT 1  
SAN ANTONIO, TX

**Date:** 1/21/2023

**WEATHER:** Cloudy  
**TEMPERATURE RANGE:** 58 °F TO 59 °F  
**PSI REPRESENTATIVE:** Benjamin Urbina

### TYPE OF INSPECTION BEING PERFORMED

#### SOILS

- ☐ FOUNDATIONS  
☐ CONTROLLED FILL (COMPACTION)  
☐

#### ASPHALT

- ☐ BATCH PLANT  
☐ PLACEMENT (JOB SITE)  
☐

#### CONCRETE

- ☐ BATCH PLANT  
☐ PLACEMENT (JOB SITE)  
☒ SPECIMEN TRANSPORT  
☒ 03113664-165, C1

#### OTHER

- ☐  
☐  
☐

### BRIEF RESUME OF WORK ACCOMPLISHED THIS DATE:

As requested, a representative of PSI reported to the above referenced project site to retrieve 1 set of 5 cylinders cast by PSI on 01/20/2023 which were transported back to the PSI laboratory for further curing and compressive strength testing.



Professional Service Industries, Inc.  
Three Burwood Lane  
San Antonio, TX 78216  
Texas Firm Registration No. F-03307  
Phone: (210) 342-9377  
Fax: (210) 342-9401

Report No: SDFR:03113664-172

Issue No: 1

These test results apply only to the specific locations and materials noted and may not represent any other locations or elevations. This report may not be reproduced, except in full, without written permission by Professional Service Industries, Inc. If a non-compliance appears on this report, to the extent that the reported non-compliance impacts the project, the resolution is outside the PSI scope of engagement.

Approved Signatory: Ernesto Gomez (Project Manager)  
Date of Issue: 2/24/2023

## Summary Daily Field Report

**Client:** ASHTON WOODS  
17319 SAN PEDRO  
SUITE 140  
SAN ANTONIO, TX 78232

**CC:**  
COLBY OLGETREE

**Project:** JUNGMAN UNIT 1  
SAN ANTONIO, TX

**Date:** 2/21/2023

**WEATHER:** Partly Cloudy  
**TEMPERATURE RANGE:** 70 °F TO 75 °F  
**PSI REPRESENTATIVE:** Colten Ruff

### TYPE OF INSPECTION BEING PERFORMED

#### SOILS

- ☐ FOUNDATIONS  
☐ CONTROLLED FILL (COMPACTION)  
☐

#### ASPHALT

- ☒ BATCH PLANT  
☐ PLACEMENT (JOB SITE)  
☒ Sample Pick up

#### CONCRETE

- ☐ BATCH PLANT  
☐ PLACEMENT (JOB SITE)  
☐ SPECIMEN TRANSPORT  
☐

#### OTHER

- ☐  
☐  
☐

### BRIEF RESUME OF WORK ACCOMPLISHED THIS DATE:

Type of Material: C/Rap  
PG Binder: 70-22  
Asphalt Plant: Texas Materials Rio Medina Plant  
Design #: PMC1604RM  
PSI Lab #: 22-039 (0-500-ton sample)  
PSI Lab #: 22-040 (500-1000-ton sample)

Please note: Results will be report on separate report.

If there are any questions concerning this report, please contact our office at your earliest convenience.

Respectfully submitted,  
Intertek-PSI



Professional Service Industries, Inc.  
Three Burwood Lane  
San Antonio, TX 78216  
Texas Firm Registration No. F-03307  
Phone: (210) 342-9377  
Fax: (210) 342-9401

Report No: SDFR:03113664-174

Issue No: 1

These test results apply only to the specific locations and materials noted and may not represent any other locations or elevations. This report may not be reproduced, except in full, without written permission by Professional Service Industries, Inc. If a non-compliance appears on this report, to the extent that the reported non-compliance impacts the project, the resolution is outside the PSI scope of engagement.

Approved Signatory: Ernesto Gomez (Project Manager)  
Date of Issue: 2/24/2023

## Summary Daily Field Report

**Client:** ASHTON WOODS  
17319 SAN PEDRO  
SUITE 140  
SAN ANTONIO, TX 78232

**CC:**  
COLBY OLGETREE

**Project:** JUNGMAN UNIT 1  
SAN ANTONIO, TX

**Date:** 2/22/2023

**WEATHER:** Partly Cloudy  
**TEMPERATURE RANGE:** 70 °F TO 75 °F  
**PSI REPRESENTATIVE:** Colten Ruff

### TYPE OF INSPECTION BEING PERFORMED

#### SOILS

- ☐ FOUNDATIONS
- ☐ CONTROLLED FILL (COMPACTION)
- ☐

#### ASPHALT

- ☒ BATCH PLANT
- ☐ PLACEMENT (JOB SITE)
- ☒ Sample Pick up

#### CONCRETE

- ☐ BATCH PLANT
- ☐ PLACEMENT (JOB SITE)
- ☐ SPECIMEN TRANSPORT
- ☐

#### OTHER

- ☐
- ☐
- ☐

### BRIEF RESUME OF WORK ACCOMPLISHED THIS DATE:

Type of Material: C/Rap  
PG Binder: 70-22  
Asphalt Plant: Texas Materials Rio Medina Plant  
Design #: PMC1604RM  
PSI Lab #: 22-041 (0-500-ton sample)  
PSI Lab #: 22-042 (500-1000-ton sample)

Please note: Results will be report on separate report.

If there are any questions concerning this report, please contact our office at your earliest convenience.

Respectfully submitted,  
Intertek-PSI



Professional Service Industries, Inc.  
Three Burwood Lane  
San Antonio, TX 78216  
Texas Firm Registration No. F-03307  
Phone: (210) 342-9377  
Fax: (210) 342-9401

Report No: SDFR:03113664-176

Issue No: 1

These test results apply only to the specific locations and materials noted and may not represent any other locations or elevations. This report may not be reproduced, except in full, without written permission by Professional Service Industries, Inc. If a non-compliance appears on this report, to the extent that the reported non-compliance impacts the project, the resolution is outside the PSI scope of engagement.

Approved Signatory: Ernesto Gomez (Project Manager)  
Date of Issue: 2/24/2023

## Summary Daily Field Report

**Client:** ASHTON WOODS  
17319 SAN PEDRO  
SUITE 140  
SAN ANTONIO, TX 78232

**CC:**  
COLBY OLGETREE

**Project:** JUNGMAN UNIT 1  
SAN ANTONIO, TX

**Date:** 2/23/2023

**WEATHER:** Partly cloudy  
**TEMPERATURE RANGE:** 66 °F TO 82 °F  
**PSI REPRESENTATIVE:** Michael Galland

### TYPE OF INSPECTION BEING PERFORMED

#### SOILS

- ☐ FOUNDATIONS  
☐ CONTROLLED FILL (COMPACTION)  
☐

#### ASPHALT

- ☐ BATCH PLANT  
☐ PLACEMENT (JOB SITE)  
☐

#### CONCRETE

- ☐ BATCH PLANT  
☐ PLACEMENT (JOB SITE)  
☒ SPECIMEN TRANSPORT  
☒ 03113664-175, C1

#### OTHER

- ☐  
☐  
☐

### BRIEF RESUME OF WORK ACCOMPLISHED THIS DATE:

As requested, a representative of PSI reported to the above referenced project site to retrieve 1 set of 5 cylinders cast by PSI on 02/22/23 which were transported back to the PSI laboratory for further curing and compressive strength testing.



Professional Service Industries, Inc.  
Three Burwood Lane  
San Antonio, TX 78216  
Texas Firm Registration No. F-03307  
Phone: (210) 342-9377  
Fax: (210) 342-9401

Report No: SDFR:03113664-177

Issue No: 1

These test results apply only to the specific locations and materials noted and may not represent any other locations or elevations. This report may not be reproduced, except in full, without written permission by Professional Service Industries, Inc. If a non-compliance appears on this report, to the extent that the reported non-compliance impacts the project, the resolution is outside the PSI scope of engagement.

Approved Signatory: Ernesto Gomez (Project Manager)  
Date of Issue: 2/27/2023

## Summary Daily Field Report

**Client:** ASHTON WOODS  
17319 SAN PEDRO  
SUITE 140  
SAN ANTONIO, TX 78232

**CC:**  
COLBY OLGETREE

**Project:** JUNGMAN UNIT 1  
SAN ANTONIO, TX

**Date:** 2/24/2023

**WEATHER:** Partly cloudy  
**TEMPERATURE RANGE:** 64 °F TO 84 °F  
**PSI REPRESENTATIVE:** Michael Galland

### TYPE OF INSPECTION BEING PERFORMED

#### SOILS

- ☐ FOUNDATIONS  
☐ CONTROLLED FILL (COMPACTION)  
☐

#### ASPHALT

- ☐ BATCH PLANT  
☐ PLACEMENT (JOB SITE)  
☐

#### CONCRETE

- ☐ BATCH PLANT  
☐ PLACEMENT (JOB SITE)  
☒ SPECIMEN TRANSPORT  
☒ C1 03113664- 176

#### OTHER

- ☐  
☐  
☐

### BRIEF RESUME OF WORK ACCOMPLISHED THIS DATE:

As requested, a representative of PSI reported to the above referenced project site to retrieve 1 set of 5 cylinders cast by PSI on 02/22/23 which were transported back to the PSI laboratory for further curing and compressive strength testing.