



SEWER MANHOLE TEST RECORDS

PROJECT NAME: Rancho Carlota unit 5

GENERAL CONTRACTOR: _____

PD JOB NO.: 12386-03UTILITY CONTRACTOR: VK KnowltonSAWS JOB NO.: 22-1726

SAWS CONTRACT NO.: _____

TESTING REQUIREMENT: 2@10

Date	Manhole I.D.	Test Type		Test Results		Pass/Fail P/F
		Hydro	Vacuum	Hydro	Vacuum	
6-21-23	E3		2@10		2@10	Pass
6-21-23	E4		2@10		2@10	Pass

REMARKS:

CONTRACTOR:

SAWS:

PAPE-DAWSON ENGINEERS, INC.:

SIGNATURE

DATE

SIGNATURE

DATE

SIGNATURE

DATE

Jason Saldana

Sean Rademacher.

6-21-23

PRINT NAME

PRINT NAME

PRINT NAME

O:\Public\WORD\Forms\PD Const\Water and Sewer Line Test Report.docx

Transportation | Water Resources | Land Development | Surveying | Environmental

telephone: 210-375-9000 address: 2000 NW LOOP 410 SAN ANTONIO, TX 78213 website: PAPE-DAWSON.COM

San Antonio | Austin | Houston | Fort Worth | Dallas Texas Engineering Firm #470 Texas Surveying Firm #10028800



WATER AND SEWER LINE TEST REPORT

PROJECT NAME: Rancho carlota unit 5

GENERAL CONTRACTOR: _____

PD JOB NO.: 12386-03UTILITY CONTRACTOR: VK KnowltonSAWS JOB NO.: 22-1726

CONTRACT NO.: _____


PIPE TYPE: SDR26SIZE: 8" 530LF

Date	Test No.	Line Section Sta. To Sta.	Begin Test		End Test		Pass/Fail P/F	Sewer Only Mandrel	Water Only Gallons Used
			Time	Psig	Time	Psig			
6-21-23		E4-E3	8:38	4	8:43	4	Pass	Pass	
6-21-23		E3-E2	8:25	4	8:30	4	Pass	Pass	

REMARKS: _____

 CONTRACTOR: 

SAWS: _____

 PAPE-DAWSON ENGINEERS, INC.: 

SIGNATURE

DATE

SIGNATURE

DATE

SIGNATURE

DATE

Jason Saldana

Sean Rademacher. 6-21-23

PRINT NAME

PRINT NAME

PRINT NAME

O:\Public\WORD\Forms\PD Const\Water and Sewer Line Test Report.docx

Transportation | Water Resources | Land Development | Surveying | Environmental

telephone: **210-375-9000** address: **2000 NW LOOP 410 SAN ANTONIO, TX 78213** website: **PAPE-DAWSON.COM**

San Antonio | Austin | Houston | Fort Worth | Dallas Texas Engineering Firm #470 Texas Surveying Firm #10028800