



3421 Paesanos Pkwy Suite 200
San Antonio, Texas 78231
P (210) 979-8444
F (210) 979-8441

WINDSONG SUBDIVISION

Field Inspector: Ben Phillips

Contractor: VK KNOWLTON

SAWS Job No.: 23-1056

Hydrostatic Test Records

Field Acceptance Date: 04.11.2025

Water Line		Pressure Test			
Waterline Pipe	Linear Footage of Pipe	PSI ~ Start	PSI ~ End	Time	Result
8" C900	6,106	200	200	4 HRS	PASS
12" C900	173	200	200	4 HRS	PASS
2" HDPE	621	200	200	4 HRS	PASS

TOTAL =	6,900	200	4 HRS	PASS
----------------	--------------	------------	--------------	-------------

Linear Footage of Pipe

PSI

Minimum Time Held

Signature: _____

Ben Phillips - KFW Engineers

Signature: _____

VK KNOWLTON